

The 8 Wastes - TIM WOODY

Transport

Move processes closer together

Inventory

Improve stock control

Movement

Have tools and materials to hand

Waiting

Balance the Line with TAKT

Over-processing

Design products for manufacture

Over-production

Introduce 1 piece flow

Defects

Use Standard Operating Procedures

Your talent

Invest and develop the team